

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L3	99	keyless with (entry door opener) and lockout	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/19 10:24
L4	536	340/5.72.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/19 10:42
L5	1549	340/5.3.ccls. 340/5.31.ccls. 340/5.61-5.64.ccls. 340/5.54.ccls. 340/426.36	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/19 10:43
L6	501	5 and (keyless fob wireless remote) and (error wrong lockout fail failure)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/19 10:44
L7	223	5 and (keyless fob wireless remote) and (error wrong lockout fail failure) same code	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/19 10:58
L8	54	5 and (keyless fob wireless remote) and (incorrect) same code	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/19 10:58
L9	19	8 not 7	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/19 11:21
L10	2124	307/10.1.ccls 307/9.1.ccls. 307/10.2.ccls. 307/10.4.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/19 11:22

S1	127	quasi-digital	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/17 17:44
S2	8	quasi-digital.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/17 18:25
S3	307	307/10.5.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/17 18:55
S4	5554	307/9.1-10.6.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/17 18:55
S5	3	S4 and (morse adj code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/17 19:00
S6	7	S4 and morse and code	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/17 19:00
S7	30	("3587051" "3593816" "3633167" "3691396" "3710316" "3751718" "3754213" "3764859" "3812403" "3831065" "3871474" "3878511" "3885408" "3893073" "4189712" "4197524" "4205325" "4206491" "4222088" "4249245").PN. OR ("4455588").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/01/17 19:03
S8	23	("3886535" "4438752" "4463340" "4477874" "4492959" "4532507" "4677284" "4688036").PN. OR ("4809199"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/01/17 19:05

S9	2994	vehicle and morse	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 08:55
S10	418	vehicle and (morse same (code signal))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 08:56
S11	185	S10 and (lock unlock)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 09:30
S12	2007284	vehicle	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 09:30
S13	3842	S12 and keyless	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 10:54
S14	2597	S13 and door	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 09:35
S15	1789	S14 and (code sequence number)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 09:36
S16	1477	S15 and (keypad switch sensor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 10:06

S17	485	307/10.3.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 09:38
S18	43	S17 and keyless	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 09:38
S19	46	("3544804" "3619633" "3670836" "3731156" "3756341" "3766400" "3784839" "3796889" "3812403" "3907060" "3968666" "3987408" "4107962" "4150731" "4232758" "4288778" "4292620" "4342024" "4360074" "4463340" "4553511" "4645939" "4682062" "4690240" "4691801" "4736113" "4738333" "4809199" "4834207" "4852680" "4888575" "4932494" "4991683" "5006843" "5041510" "5079435" "5138986" "5193641" "5481253" "5547039" "5561332" "5583383" "5640057" "5821631").PN. OR ("6236120"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/01/18 09:42
S20	358	S16 and door with handle	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 10:30
S21	21	("20030095416" "3908149" "4041301" "4898010" "4983947" "5297010" "5651163" "5828299" "5844470" "5952731" "5960942" "6070998" "6075294" "6084317" "6098433" "6135621" "6158867" "6164805" "6367295" "6378344" "6550946").PN. OR ("6854870"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/01/18 10:20
S22	6	S12 and (unlock with keypad with door with handle)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 10:39

S23	32	S12 and (unlock with keypad) and (door with handle)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 10:33
S24	26	S23 not S22	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 10:33
S25	164	S12 and (unlock with (code switch button) with door with handle)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 10:47
S26	0	S12 and (unlock with (keypad) with handle) not S22 not S23	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 10:48
S27	13	S12 and (code with keypad with door with handle)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 10:48
S28	130	S12 and door with (unlock lock locked locking unlocked unlocking) with keypad	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 10:55
S29	477	S12 and (unlock lock locked locking unlocked unlocking) with keypad	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 10:56
S30	254	S12 and ((unlock lock locked locking unlocked unlocking) with door) same keypad	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 10:57

S31	73	S30 and (LED optical acoustic) same (time flash flashing indication)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 11:03
S32	6840	S12 and (LED optical acoustic) same (time flash flashing indication) same (code input)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 11:20
S33	291	S32 and door with (unlock lock)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 11:05
S34	4759	S12 and (LED optical acoustic) same (flash flashing blink blinking frequency) same (code input)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 11:33
S35	2	"20030002716".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 11:21
S36	235	S34 and door with (unlock lock)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 11:34
S37	9164	S12 and (LED optical acoustic light sound) same (flash flashing blink blinking frequency) same (code input)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 11:34
S38	497	S37 and door with (unlock lock)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 15:28

S39	349	S38 and (keyless or keypad or tactile proximity)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 11:35
S40	13	("4672375" "5079435" "5319364" "5751072" "5783994" "5905431" "6031465" "6034617" "6181254" "6236333").PN. OR ("6606492").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/01/18 15:25
S41	211	"4" and (invalid incorrect wrong) with code same time same (fob wireless transmitter)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 15:28
S42	2007284	vehicle	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 16:16
S43	127	S42 and (invalid incorrect wrong) with code same (fob wireless transmitter)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 16:11
S44	53	S43 and door with (unlock lock)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 16:11
S45	622	S42 and (invalid incorrect wrong error) with code same (fob wireless transmitter)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 16:16
S46	72	S43 and door	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 16:11
S47	19	S46 not S44	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 16:11

S48	66	(door with (unlock lock)) and (invalid incorrect wrong) with code same (fob wireless transmitter)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 16:12
S49	13	S48 not S44	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 16:12
S50	71	S42 and lockout and (invalid incorrect wrong error) with code and (fob wireless transmitter)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 16:23
S52	386	S42 and (invalid incorrect wrong error) with code and doors with (lock unlock)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 16:25
S53	299	S52 not (S46 S47 S48 S49 S50)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/18 16:25